

# Gloucester St. Sluices Painting Friends of Gumstool Brook 9<sup>th</sup> August 2024

Photos taken during maintenance painting work  
undertaken by Friends of Gumstool Brook volunteers  
at Gloucester St. Sluices in cooperation with  
Cirencester Town Council

[AS, JT, NB & NE]

<https://gumstool.org.uk/>



Gloucester St Sluices and pedestrian bridge needed a coat of paint.....

The Friends of Gumstool Brook volunteered to clean and paint the ironwork in cooperation with Cirencester Town Council.



There are three sluice gates at the weir, plus a pedestrian bridge with iron railings.







Preparation involved wire brushing and sanding the iron railings and sluice gate frames to remove the rust and loose paint.





The team painted the railings and sluice frames with 2 coats of metal paint provided by Cirencester Town Council.







The team completed the painting, cleared up the worksite and left the sluice gates and footbridge now looking much smarter.

